

TWR- 50060

THE EFFECTS OF AUTOCLAVE CURE TEMPERATURES ON NON-SILICONE TEFLON TAPE WITH EPDM RUBBER

FINAL REPORT

OCTOBER 1989

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION GEORGE C. MARSHALL SPACE FLIGHT CENTER MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No. NAS8-30490

DR. No.

Type 5-6

WBS.No.

4B 201



P.O. Box 707, Brigham City, UT 84302-0707 (801) 863-3511

(NASA-CR-163682) THE EFFECTS OF AUTUCLAVE CURE TEMPSKATURES ON NON-SILICURE FEELIN TAPE WITH EPOM SUPEER Final Report (Thiokol Corp.) 14 p

N90-70701

Unclas 00/20 0271087 DOC NO.

VOL REV

TITLE

TWR-50060 PEI-966

THE EFFECTS OF AUTOCLAVE CURE TEMPERATURES ON NON-SILICONE TEFLON TAPE WITH EPDM RUBBER

FINAL REPORT

OCTOBER 1989

PREPARED BY

DIANE L. COUNTRYMAN
MIXING AND CASTING PROCESSING

APPROVED BY

R. C. Raisor

Spectrochemical Analysis

T. F. Christensen, Manager

Process Engineering

J. M. Jewell, Supervisor

Mixing and Casting Processing

P. C. Petty, Manager

Case Preparation Engineering

Program Manager

Release

Thickol CORPORATION

SPACE OPERATIONS

P.O. Box 707, Brigham City, UT 84302-0707 (801) 863-3511

Program/Manager



CONTENTS

		Page			
1.0	INTRODUCTION AND SUMMARY	1			
2.0	CONCLUSIONS	2			
3.0	RECOMMENDATIONS	2			
4.0	NARRATIVE	2			
	FIGURES				
1.	Cross-Section Of T-Section Layup	3			
2.	Cross-Section Of T-Section Model	4			
3.	Placement Of Non-Silicone Teflon Tape	5			
	TABLE				
I.	T-Section Model Autoclave Cure	6			
	ATTACHMENTS				
I.	FT-IR Analysis Of EPDM Rubber	7			
II.	FT-IR Analysis Of EPDM Rubber On Control Model	8			
III.	FT-IR Analysis Of EPDM Extrusion On 3-In. Tape Model	9			
IV.	FT-IR Analysis Of 3-In. Non-Silicone Teflon Tape	10			
٧.	FT-IR Analysis Of EPDM Under 2-In. Tape	11			
DISTRIBUTION					
Reference	ce: Work Request No. F89044 LWR No. 591274 LWR No. 591280 Laboratory Log No. 08-18-89-27175				
Process Engineering Technical Report Categories					
Curing Manufact	Heat turing Processes Stiffener Rings				
Rubber,					
Teflon	Temperature				

	TWR-50060	
VISION	DOC NO.	VOL
	SEC PAC	i



1.0 INTRODUCTION AND SUMMARY

The effect of elevated autoclave cure temperatures on non-silicone Teflon tape caused a bonding of the adhesive to EPDM rubber. There was adhesive failure between the tape backing and the tape adhesive on all samples. Therefore, this tape (Stock Nos. 57-742361, 57-742362, 57-742363) is not recommended for the use of securing cowl plates to EPDM rubber extrusions during the cure cycle.

The T-sections comprising the stiffener rings are 12.5 ft long. Three T-sections complete one stiffener ring. Two different EPDM rubber extrusions (#6100 and #5822) are used to cover the T-sections. The U-shaped covers the outside of the T-top and the angled-shaped covers the insides of the stem (Figure 1). Cowl plates are placed on all three sides of the T-top with silicone Teflon tape approximately every 1-2 feet (tape is 2-in. long), to hold the cowl plates in place during the autoclave cure cycle. These cowl plates have been known to shift toward the center (t-bar), and cut into the EPDM rubber.

RSRM Manufacturing Engineering requested the testing of a nonsilicone Teflon tape during the autoclave cure cycle to determine:

- 1. The effects of heat on the non-silicone Teflon tape.
- 2. The ability of the tape to hold the cowl plates in place during cure.

After heating, the tape was extremely difficult to remove and had to be scraped and peeled away with razor and tweezers. The rubber underneath the peeled tape showed a significant color change of a khaki tan, rather than the normal black as in the other non-taped areas. The FT-IR spectrum for this area was the same as that for the FT-IR spectrum done on the tape alone (Attachments IV and V). EPDM not under the tape matched that of normal EPDM (Attachments I, II, and III).

There were no signs of any shifting on all three models.

TWR-50060		
DOC NO.		VOL
SEC	PAGE	1



2.0 CONCLUSION

The effect of high cure temperature was that the non-silicone Teflon tape was very difficult to remove and left the adhesive bonded on the EPDM rubber. Only the tape backing could be peeled off.

3.0 RECOMMENDATION

It is recommended that non-silicone Teflon tape <u>NOT</u> be used to secure cowl plates to EPDM rubber. However, polyester and hydrocarbon tapes, also, are not silicone and should be investigated.

4.0 **NARRATIVE**

Steel plates were spot welded together (Figure 2) on one side only to form a T-section model of the stiffener rings. Three models were made, each 12-in. long.

EPDM extrusion scraps from M-52 were used for layup of the models. Aluminum cowl plates were cut to size, cleaned with TCA, and wrapped in Teflon tape. The 205/236A Chemlok system was sprayed on the T-section models with the 2-in. and 3-in. width non-silicone Teflon tapes being used as follows:

Model 1: Control

No tape used.

Model 2: 2-in. Tape

Tape was applied as a continuous solid strip across the length of the T-bar and the T-top edge on the long extrusion side. The short extrusion side had no tape along the T-bar length and intermittently (2-in. ends and middle only) on the T-top edge (Figure 3).

Model 3: 3-in. Tape

Tape applied the same as Model 2.

Dacron patterning cloth, Stern #7777, and the green nylon vacuum film were used for vacuum bagging. The cure of Table I was used. After cure, small sections of rubber were cut for ATR/FT-IR spectrum analysis as was the non-silicone Teflon tape.

TWR-50060		
DOC NO.		VOL
SEC	PAGE	2






Figure 1. Cross-Section of T-Section Layup

"PE408"

| TWR - 50060 | VOL | | SEC | PAGE 3







Figure 2. Cross-Section of T-Section Modei


"PE409"

| TWR-50060 | VOL | | SEC | PAGE | 4





Long Extrusion Side



Short Extrusion Side

Cross-hatching represents tape. Yellow represents EPDM rubber.

Figure 3. Placement of Non-Silicone Teflon Tape

	TWR-50060		"PE4!0"
REVISION	DOC NO.		VOL
	SEC	PAGE	5





REVISION _

Table I. T-Section Model Autoclave Cure


M-86 AUTOCLA	WES.			Sc	N 312F		13246	
SRM						DIANNE	COUNT	TRYMAN
D.Kl. DARLEY				Contro	•••			
COMMENTS	SEG NO.	PRO	FRE 2	SLG TIME	EVENTS	CYCLES	MEST . STEP	CROUP
•	1	100	0	12	OFF	0	2	1
	2		0	30	OFF	0	3	1
	3	+	105	133	OFF	0	4	
	4	+	105	30	1	0 ·	5	
	5		201	30	OFF	٥	6	
	6	292		155	OFF	0	7	
BHPS. 40MIN	7	8	105	60	OFF	0	8	-
	8	8		10	off.	0	9	
	9	8	0	60	OFF	0	10	
	10	100	0	.2	3	0	10	
	•							
					\$		<u> </u>	
								1
						<u> </u>		
								-
							-	-








	TWR-50060			
EVISION	DOC NO.			
	SEC	PAGE 7		





TWR - 50060

DOC NO. VOL

SEC PAGE 10

Thickol CORPORATION SPACE OPERATIONS 10:59:59 222 Aug 89 600.00 LWR 591280.003 FT-IR Analysis of EPDM Under 2-In. Tape ATR CLAMPED, WAVENUMBERS (CM 2200.0 2 INCH SAMPLE Attachment V. 3000.0 12" LONG T-SECTIONS, 3800.0

TWR-50060

DOC NO. | VOL

SEC | PAGE | 11

7677 0

VB20KBANCE

9102.0

0.3740

7977 0

8991 0

7790 0

6110.0